

EAST Search History**EAST Search History (Prior Art)**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	5	((Blumberg near2 Manfred) (Dirrichs near2 Stefan) (London near2 Wolfgang) (Topfer near2 Gary)).in.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:24
S2	1	((Blumberg near2 Manfred) (Dirrichs near2 Stefan) (London near2 Wolfgang) (Topfer near2 Gary)).in. AND (machine near tool with encod\$4).clm.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:25
S3	1	(726/27.ccls.) AND (machine near3 tool).clm.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:26
S7	5	("726"/\$.ccls.) AND (machine with tool with (encod\$4 encrypt\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:28
S9	15	("713"/\$.ccls.) AND (machine with tool with (encod\$4 encrypt\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:29
S10	1514	(prevent\$4 with (operating operation control\$4) with (machine near2 tool))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:31
S11	2	((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4) near7 (operat\$4 control\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath \$4)) with (encrypt\$4 encod \$4 \$4cipher\$)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 08:43

S12	12	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4) near7 (operat\$4 control\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4 CNC)) same (encrypt\$4 encod\$4 \$4cipher \$\$)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 08:57
S13	24	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4 CNC)) same (encrypt\$4 encod\$4 \$4cipher \$\$)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:01
S15	34	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4 CNC)) same ((encrypt\$4 encod\$4 \$4cipher \$\$) password (decrypt\$4 decod\$4))) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:03
S17	32	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with ((machine device) near2 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher \$\$)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:10
S18	36	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher \$\$)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:11

S19	67	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4 \$4proper\$4) with (operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:12
S20	33	S19 not S15	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:12
S21	1165	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:22
S22	626	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:23
S23	531	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:23
S24	525	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:23

S25	243	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard \$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:24
S26	61	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4). ab.) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:24
S27	87	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard \$4)) AND (@ad< "20031017") AND (operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)).ab.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:28
S28	102	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard \$4)) AND (@ad< "20031017") AND (operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:28

		drilling grinding milling lath \$4 CNC threading).clm.				
S29	68	S27 not S26	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:28
S30	33	S28 not S27	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:34
S31	243	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard \$4)) AND (@ad< "20031017") AND (operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:48
S32	243	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard \$4)) AND (@ad< "20031017") AND ((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:51

S34	2	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard \$4)) AND (@ad< "20031017") AND ((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) same (encrypt\$4 decrypt\$4 encod \$4 decod\$4 \$4cipher\$4) same key)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:52
S35	6	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND ((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) same (encrypt\$4 decrypt\$4 encod \$4 decod\$4 \$4cipher\$4) same key) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:53
S36	6	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4) AND (((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) same (encrypt\$4 decrypt\$4 encod \$4 decod\$4 \$4cipher\$4) same key) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:55

S37	41	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((encrypt\$4 encrypt\$4 encod \$4 decod\$4 \$4cipher\$4) same key) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:55
S38	38	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((encrypt\$4 encrypt\$4 encod \$4 decod\$4 \$4cipher\$4) with key) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:55
S39	10	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((encrypt\$4 encrypt\$4 encod \$4 decod\$4 \$4cipher\$4) with key) AND (@ad< "20031017") AND (not Ginter.in.)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:57
S40	6	("4405829" "4981402").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 15:16
S41	28	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) same (public near2 key)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:37

S45	265	((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:45
S46	80	((control\$4 operat\$4 activat\$4 start\$4) with (machine near5 (tool drilling grinding milling lath\$4 CNC threading))) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:46
S48	52	((control\$4 operat\$4 activat\$4 start\$4) with (machine near5 (tool drilling grinding milling lath\$4 CNC threading))) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (not S41) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:47
S49	1	10/575524	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 11:14
S64	260	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter))) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 11:23
S65	4	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter)) with signature) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 11:25

S66	5	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter)) with signature) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:08
S67	231	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND (signature) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:09
S68	231	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND (signature) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)) AND signature AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:10
S69	28	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND (signature) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)).clm. AND signature AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:10

S70	28	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND (signature) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)).clm. AND signature AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:11
S71	28	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine tool drilling grinding milling lath\$4 CNC threading car) with ((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND (signature) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)).clm. AND signature AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:16
S72	556	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine (tool drilling grinding milling lath\$4 CNC threading car)) with (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:43
S73	66	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine (tool drilling grinding milling lath\$4 CNC threading car)) with (encrypt\$4 decrypt\$4)) AND ((encrypt\$4 decrypt\$4) with (command\$4 parameter) with (control\$4 operat\$4 activat\$4 start\$4 runn\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 13:44
S76	37	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine) near3 (tool drilling grinding milling lath\$4 CNC threading)) AND (((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND ((encrypt\$4 decrypt\$4) near5 (command control\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 15:39

S78	10	((secur\$4 safe\$4 protect\$4) with (control\$4 operat\$4 activat\$4 start\$4) near5 (machine) near3 (tool drilling grinding milling lath\$4 CNC threading)) AND (((control\$4 operat\$4 activat\$4) near3 (code parameter command))) AND (encrypt\$4 decrypt\$4) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 15:42
S79	5	"700"/\$.ccls. AND ((secur\$4 safe\$4 protect\$4) with (control\$4 operat\$4 activat\$4 start\$4) near5 (machine) near3 (tool drilling grinding milling lath\$4 CNC threading)) AND (encrypt\$4 decrypt\$4) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/01 15:46
S80	2	(gen near2 lin).in. AND (machine near2 tool)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/02 10:04
S81	2	((control\$4 operat\$4 activat\$4 start\$4) near5 (machine) near3 (tool drilling grinding milling lath\$4 CNC threading) same (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/02 10:16
S84	27	((machine near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 decrypt\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/02 10:23
S87	7	("4405829" "4981402").pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/02 14:41

S88	29	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4 password)) AND (signature with (operat\$6 activat\$4 control\$4 work\$4 start\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/06 10:10
S89	30	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4 password)) AND (signature with (operat\$6 activat\$4 control\$4 work\$4 start\$4 protect\$4 authoriz\$6)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/06 10:23
S90	83	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4 password)) AND ((id identification name signature) with (operat\$6 activat\$4 control\$4 work\$4 start\$4 protect\$4 authoriz\$6)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/06 11:18
S91	38	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4 password)) AND (((id identification name signature) near5 (user operator sender client)) with (operat\$6 activat\$4 control\$4 work\$4 start\$4 protect\$4 authoriz\$6)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/06 11:19

S92	38	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4 password) AND (((id identification name signature) near5 (user operator sender client administrator)) with (operat\$6 activat\$4 control\$4 work\$4 start\$4 protect\$4 authoriz\$6)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/06 11:19
S93	1	10/575524 AND (private near3 key)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/08 08:00
S94	5	"4405829".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/08 21:54
S95	616	(signature with encrypt\$4 with (private near2 key)) AND (verif\$8 near4 signature with decrypt\$4 with (public near2 key)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/08 22:05
S96	51	((sign\$4 signature) with encrypt\$4 with (private near2 key)) AND (verif\$8 near4 (signature sign\$4) with decrypt\$4 with (public near2 key)) AND ((user client operator client) near4 (id identification name) near5 (operating operat\$3 authenticat\$4 control\$4 start\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/08 22:09

S97	6	((sign\$4 signature) with encrypt\$4 with (private near2 key)) AND (verif\$8 near4 (code command parameter control\$4 program instruction application) with decrypt\$4 with (public near2 key)) AND ((user client operator client) near4 (id identification name) near5 (operating operat\$3 authenticat\$4 control\$4 start\$4)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/08 22:12
S98	10	"7602913".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/09 14:56
S99	18	((sign\$4 signature) with encrypt\$4 with (private near2 key)) AND (verif\$8 near4 (code command parameter control\$4 program instruction application) with decrypt\$4 with (public near2 key)) AND ((user client operator client) near4 (id identification name)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/09 21:02
S100	19	((sign\$4 signature) with (encrypt\$4 encod\$4) with (private near2 key)) AND (verif\$8 near4 (code command parameter control\$4 program instruction application) with (decrypt\$4 decod\$4) with (public near2 key)) AND ((user client operator client) near4 (id identification (user adj name))) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/09 21:24

S101	15	((sign\$4 signature) with (code command parameter control\$4 program instruction application) with (private near2 key)) AND ((verif\$8 near4 (code command parameter control \$4 program instruction application) with (decrypt\$4 decod\$4) with (public near2 key)) AND ((user client operator client) near4 (id identification (user adj name))) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/09 21:29
S102	176	((sign\$4 signature) with (code command parameter control\$4 program instruction application) with ((private near2 key) (encod \$4 encrypt\$4)) AND ((verif \$8 validat\$4 authenticat\$4) near4 (code command parameter control\$4 program instruction application) with ((decrypt\$4 decod\$4) (public near2 key))) AND ((user client operator client) near4 (id identification (user adj name)) with (operating operation start\$4 activat\$4 work\$4 control\$4)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/09 21:31
S103	65	((sign\$4 signature) with (code command parameter control\$4 program instruction application) with ((private near2 key) (encod \$4 encrypt\$4)) AND ((verif \$8 validat\$4 authenticat\$4) near4 (code command parameter control\$4 program instruction application) with ((decrypt\$4 decod\$4) (public near2 key))) AND ((user client operator client) near4 (id identification (user adj name)) with (operating operation start\$4 activat\$4 work\$4 control\$4) with (machine tool device apparatus)) AND (@ad< "20031017")	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/09 21:40

S104	6	((sign\$4 signature encrypt\$4 encod\$4) near6 (code command parameter control \$4 program instruction application software) with (private near2 key)) AND ((verif\$8 validat\$4 authenticat\$4) near5 (code command parameter control \$4 program instruction application software) with ((decrypt\$4 decod\$4) near5 (public near2 key))) AND ((user client operator client) near4 (id identification (user adj name)) with (operating operation start\$4 activat\$4 work\$4 control\$4) with (machine tool device apparatus)) AND (@ad< "20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/03/10 09:11
------	---	--	---	----	----	---------------------

EAST Search History (Interference)

<This search history is empty>

3/ 10/ 2010 3:17:26 PM

C:\ Documents and Settings\ lpham7\ My Documents\ EAST\ Workspaces\ 10\ 10-575-524.wsp